

<b>PRODUCT LINE:</b>	ACCESS		
<b>PRODUCT NAME:</b>	OMNIS		
<b>MODEL(S):</b>	E100 / E100-S Controller	<b>CATEGORY:</b>	RELEASE
<b>CONTACT:</b>	Local Technical Support	<b>DATE:</b>	2019-12-16

A new Firmware, 7.4.55, for the E100 Central Controller and E100 Satellite Controller is now available.

**This release includes:**

- Support for backbone communication between E100 controllers
- Support for Keypads M5 and M6
- Performance enhancements.

The supported new features require the Firmware in the E100/E100-S to be updated. This should be done using an SD-card image rather than using the hotfix file. To achieve the full performance enhancement, the Firmware of the LON board must be updated as well.

It is recommended to update both the E100/E100-S FW and the LON board FW at the same time.

If deciding to do the update, please contact Technical Support for full instructions on how it's best performed.

The current stock of E100 and E100-S controllers is updated to the above version.