

PRODUCT LINE: ACCESS

PRODUCT NAME: ACT365

MODEL: 1.01.34

CATEGORY: UPDATE

CONTACT: Local Technical Support


DATE: 2019-09-25

Due to the growth ACT365, we have identified a limitation and consequently, we have increased the number of time zones within ACT365.

Time zones are used for all time related actions.

Vanderbilt strongly recommend that all ACT365 ACU's should be updated to the latest firmware version 1.01.34. The latest firmware can be accessed directed from the ACT365 portal.

To perform the firmware upgrade. Enter the ACT365 ACUs on the customer portal, select the ACU's you wish to upgrade and select "Update Firmware" from the dropdown menu and click "apply".



After selecting "Apply", you will see a pop-up window where you can confirm the application.

