

PRODUCT LINE: INTRUSION

PRODUCT: SPC

MODEL: SPC 3.12 Firmware **CATEGORY:** NEW RELEASE

CONTACT: Local Technical Support **DATE:** 2020-11-11

Vanderbilt is pleased to release the new SPC firmware 3.12 on 13 November 2020. The firmware includes several enhancements and minor bug fixes.

SPC Firmware 3.12 – New features and enhancements:

- SPC region “Belgium” default settings changed to comply to the latest INCERT standard.
- Re-introduce TLS 1.2 option (default: http - Activating this option may prevent your browser from connecting to the SPC panel).
- SPC Panel Start-up Wizard change: SPC Connect connection default value changed to disabled. This will prevent customers from inadvertently enabling the option and setting up an ATS connection to SPC Connect.
- EDP alarm transmission – bug fixed:
 - We encountered a rare issue with EDP alarm transmission.
 - Please check out the release notes document to get more information about the circumstances and the available workarounds by [clicking here](#).
- Minor bug fixes and performance enhancements.

For more information, please check out the release note document.

Approval status:

EN	VdS	SBSC	SES	NF	Incert
Approved	Pending	Pending	Pending	Approved	Pending

Remark:

NF/EN certification will not state the firmware version.

How to get it?

Please visit our [Download Center](#) to download the latest SPC Firmware package.

Marketing tools

SPC Panel FW 3.12 Matrix: [EN](#)

[YouTube Channel](#) (EN only)

[Landing page](#) (EN only)