

**PRODUCT LINE:** ACCESS

**PRODUCT:** ACTpro

**MODEL:** 4000 two door controller      **CATEGORY:** SALES STOP

**CONTACT:** Michael Moyna      **DATE:** 2020-11-18

The Decal on the ACTpro-4000 has the **X** and ✓ in the wrong position (✓ should be on the bottom-right button).

All ACTpro-4000s are on sales stop with immediate effect and will be returned to Vanderbilt for replacement decals.



*Incorrect placement of X and ✓*



*Correct placement of X and ✓*